

Příloha 8

Proces termálního tváření



Make a hole and form a bush in one operation. Standard drilling machines can be used, or we can supply.



Frictional heat is generated by speed and pressure so that the material can be formed.



Fast - only takes one second plus one second for every millimetre of material thickness.



The completed bush gives additional support as a bearing for a thread.



Threads are produced by roll forming. No material is removed.



Strong connections with no parts to break free.