

A2.09	KONFERENČNÁ MIESTNOSŤ	35,14				ČAS	8	9	10	11	12	13	14	15	16	12	0,96	1,58	3,32		
			S	-	-	$I_{OS} [W.m^{-2}]$	100	117	130	139	141	139	130	117	100						
						$I_{DS} = A_S \cdot I_{OS} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			J	-	-	$I_{OJ} [W.m^{-2}]$	128	230	335	409	435	409	335	230	128						
						$I_{DJ} = A_J \cdot I_{OJ} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			V	-	-	$I_{OV} [W.m^{-2}]$	539	505	389	232	141	139	130	117	100						
						$I_{DV} = A_V \cdot I_{OV} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			Z	9,75	0,15	$I_{OZ} [W.m^{-2}]$	100	117	130	139	141	232	389	505	539						
						$I_{DZ} = A_Z \cdot I_{OZ} \cdot s [W]$	146,25	171,11	190,13	203,29	206,21	339,30	568,91	738,56	788,29						
			H	-	-	$I_{OH} [W.m^{-2}]$	379	534	640	706	729	706	640	534	397						
						$I_{DH} = A_H \cdot I_{OH} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
						$\Sigma I_D = Q_W$	146,25	171,11	190,13	203,29	206,21	339,30	568,91	738,56	788,29						
A2.11	ČITÁREŇ	24,49				ČAS	8	9	10	11	12	13	14	15	16	4	0,32	0,52	1,37		
			S	-	-	$I_{OS} [W.m^{-2}]$	100	117	130	139	141	139	130	117	100						
						$I_{DS} = A_S \cdot I_{OS} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			J	-	-	$I_{OJ} [W.m^{-2}]$	128	230	335	409	435	409	335	230	128						
						$I_{DJ} = A_J \cdot I_{OJ} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			V	6,50	0,15	$I_{OV} [W.m^{-2}]$	539	505	389	232	141	139	130	117	100						
						$I_{DV} = A_V \cdot I_{OV} \cdot s [W]$	525,53	492,38	379,28	226,20	137,48	135,53	126,75	114,08	97,50						
			Z	-	-	$I_{OZ} [W.m^{-2}]$	100	117	130	139	141	232	389	505	539						
						$I_{DZ} = A_Z \cdot I_{OZ} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			H	-	-	$I_{OH} [W.m^{-2}]$	379	534	640	706	729	706	640	534	397						
						$I_{DH} = A_H \cdot I_{OH} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
						$\Sigma I_D = Q_W$	525,53	492,38	379,28	226,20	137,48	135,53	126,75	114,08	97,50						
A2.12	ODDYCHOVÁ MIESTNOSŤ/ DETSKÝ KÚTIK	64,08				ČAS	8	9	10	11	12	13	14	15	16	12	0,96	0,72	2,99		
			S	-	-	$I_{OS} [W.m^{-2}]$	100	117	130	139	141	139	130	117	100						
						$I_{DS} = A_S \cdot I_{OS} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			J	-	-	$I_{OJ} [W.m^{-2}]$	128	230	335	409	435	409	335	230	128						
						$I_{DJ} = A_J \cdot I_{OJ} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			V	16,25	0,15	$I_{OV} [W.m^{-2}]$	539	505	389	232	141	139	130	117	100						
						$I_{DV} = A_V \cdot I_{OV} \cdot s [W]$	1313,81	1230,94	948,19	565,50	343,69	338,81	316,88	285,19	243,75						
			Z	-	-	$I_{OZ} [W.m^{-2}]$	100	117	130	139	141	232	389	505	539						
						$I_{DZ} = A_Z \cdot I_{OZ} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			H	-	-	$I_{OH} [W.m^{-2}]$	379	534	640	706	729	706	640	534	397						
						$I_{DH} = A_H \cdot I_{OH} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
						$\Sigma I_D = Q_W$	1313,81	1230,94	948,19	565,50	343,69	338,81	316,88	285,19	243,75						
A2.08	ODDYCHOVÁ MIESTNOSŤ/ HERŇA	37,55				ČAS	8	9	10	11	12	13	14	15	16	4	0,64	0,39	1,82		
			S	-	-	$I_{OS} [W.m^{-2}]$	100	117	130	139	141	139	130	117	100						
						$I_{DS} = A_S \cdot I_{OS} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			J	-	-	$I_{OJ} [W.m^{-2}]$	128	230	335	409	435	409	335	230	128						
						$I_{DJ} = A_J \cdot I_{OJ} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			V	-	-	$I_{OV} [W.m^{-2}]$	539	505	389	232	141	139	130	117	100						
						$I_{DV} = A_V \cdot I_{OV} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			Z	9,75	0,15	$I_{OZ} [W.m^{-2}]$	100	117	130	139	141	232	389	505	539						
						$I_{DZ} = A_Z \cdot I_{OZ} \cdot s [W]$	146,25	171,11	190,13	203,29	206,21	339,30	568,91	738,56	788,29						
			H	-	-	$I_{OH} [W.m^{-2}]$	379	534	640	706	729	706	640	534	397						
						$I_{DH} = A_H \cdot I_{OH} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
						$\Sigma I_D = Q_W$	146,25	171,11	190,13	203,29	206,21	339,30	568,91	738,56	788,29						
A2.14	KUCHYNKA	38,30				ČAS	8	9	10	11	12	13	14	15	16	13	1,04	3,64	5,93		
			S	-	-	$I_{OS} [W.m^{-2}]$	100	117	130	139	141	139	130	117	100						
						$I_{DS} = A_S \cdot I_{OS} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			J	19,11	0,15	$I_{OJ} [W.m^{-2}]$	128	230	335	409	435	409	335	230	128						
						$I_{DJ} = A_J \cdot I_{OJ} \cdot s [W]$	366,96	659,38	960,40	1172,55	1247,09	1172,55	960,40	659,38	366,96						
			V	-	-	$I_{OV} [W.m^{-2}]$	539	505	389	232	141	139	130	117	100						
						$I_{DV} = A_V \cdot I_{OV} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			Z	-	-	$I_{OZ} [W.m^{-2}]$	100	117	130	139	141	232	389	505	539						
						$I_{DZ} = A_Z \cdot I_{OZ} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			H	-	-	$I_{OH} [W.m^{-2}]$	379	534	640	706	729	706	640	534	397						
						$I_{DH} = A_H \cdot I_{OH} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
						$\Sigma I_D = Q_W$	366,96	659,38	960,40	1172,55	1247,09	1172,55	960,40	659,38	366,96						
A2.07	KANCELÁRIA	26,13				ČAS	8	9	10	11	12	13	14	15	16	2	0,16	0,53	1,22		
			S	-	-	$I_{OS} [W.m^{-2}]$	100	117	130	139	141	139	130	117	100						
						$I_{DS} = A_S \cdot I_{OS} \cdot s [W]$	0	0	0	0	0	0	0	0	0						
			J	-	-	$I_{OJ} [W.m^{-2}]$	128	230	335	409	435	409	335	230	128</						